Welding Safety

and Health

## **Digital Elite Series**Auto-Darkening Welding Helmets

Quick

Viewing Area

9.22 sq. in. (59.48 sq. cm)

Weld, cut, grind and X-Mode" Operating Modes

Specs

Weld: 8-13 Shades

Sensors 4 Cut: 5-8

TIG Rating 5 amps and below

Switching Speed 1/20,000 second

Weight 18 oz. (510 g)



welding and light states. not welding — keeping lighter light state while maximizing safety and **Fechnology** optimizes contrast and clarity in 1/1/1/2 optical clarity rating allows for a ClearLight" Lens the helmet downproductivity.



lens before welding starts and low-amperage lens opening Four arc sensors and four modes: weld, cut, grind and X-Mode. X-Mode prevents sunlight from darkening the from obstructed sensors.

settings and a pivoting extensive adjustability top for better fit and Headgear provides comfort.



Digital controls easily allow welder to adjust shade, delay and

Auto-on/off power control triggers lens at the strike of sensitivity.

Meets ANSI Z87.1+, CSA (Cat®-CE, AS NZ) standards.



http://willeelectric.com 209-527-6800

Auto-darkening lens is warranted for three years.